



Shire of Mundaring Asbestos Register - ACM Property

Compiled: February 2024

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
5/02/2024	Boya Oval Change Rooms & Toilet, 119 Scott Street, Boya WA 6056	Boya	1007BDNA2B	1007BDNA2B	Oval Change Rooms - Flue/Vent Pipe	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Boya Oval Change Rooms & Toilet, 119 Scott Street, Boya WA 6056	Boya	1007BDNA2B	1007BDNA2B	Home & Away Change Rooms, Kiosk - Ceilings throughout building	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Boya Oval Change Rooms & Toilet, 119 Scott Street, Boya WA 6056	Boya	1007BDNA2B	1007BDNA2B	Eaves (rear of building) - panels	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Boya Oval Change Rooms & Toilet, 119 Scott Street, Boya WA 6056	Boya	1007BDNA2B	1007BDNA2B	Male Toilet Urinal - Blackjack spray resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Boya Oval Change Rooms & Toilet, 119 Scott Street, Boya WA 6056	Boya	1007BDNA2B	1007BDNA2B	Car Park, Park/PAW - Fencing	250	YES	Damaged and deteriorating	Yes	HIGH	Remove vegetation from fence to prevent material from becoming friable. Remove and replace with non ACM product.	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Shire to coordinate with homeowner over ACM hazard and suitable control measures. Remove vegetation from all fencing. Remove and replace with non ACM product.	5/08/2024	CEO	5/02/2025
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Outside Toilet - Panels	4	YES	Intact, not friable	No, if undisturbed	LOW	Seal damaged panel to bottom corner to the right of door, otherwise monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal damaged panel to the right of door	5/08/2024	CEO	5/02/2025
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Rear Enclosed Lean To Ceiling - Panels	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Rear Enclosed Lean To Walls - Panels	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Kitchen Floor - Linoleum	20	YES	Damaged and deteriorating	Yes	HIGH	Restrict access to competent personnel. Testing required. Remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Restrict access to competent personnel. Conduct testing to determine the presence of ACM	5/05/2024	CEO	5/02/2025
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Kitchen Cooker Alcove - Tilux	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Station Masters House - Glen Forrest, 2 Railway Parade, Glen Forrest WA 6071	Glen Forrest	1149BDNA2B	1149BDNA2B	Gable Partition Front of Building - Panels	5	YES	Intact, not friable	No, if undisturbed	LOW	Remove vegetation and materials stored against panels to prevent damage and ACM becoming friable. Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Remove vegetation and materials stored against panels	5/05/2024	CEO	5/02/2025
5/02/2024	Glenn Forrest Hall, Lot 342 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA5B	1122BDNA5B	Storeroom Window Right of Stage - Window Putty	1	YES	Damaged and deteriorating	Yes	HIGH	Testing required. Seal or remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Conduct testing to determine the presence of ACM. Seal or remove and replace with non-ACM product	5/05/2024	CEO	5/02/2025
5/02/2024	Glenn Oval Change Rooms, Lot 94 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA2B	1122BDNA2B	Home Change Room Urinals - Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Glenn Oval Change Rooms, Lot 94 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA2B	1122BDNA2B	Away Change Room Urinal Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Bilgoman Aquatic Centre - Kiosk & Change Rooms, Lot 556 Lionel Road, Darlington WA 6070	Darlington	1116BDNA3B	1116BDNA3B	Male Change Room Urinal - Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Bilgoman Aquatic Centre - Plant Room, Lot 556 Lionel Road, Darlington WA 6070	Darlington	1116BDNA2B	1116BDNA2B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
5/02/2024	Darlington Bushfire Brigade, 5-13 Pine Terrace, Darlington WA 6070	Darlington	1065BDNA1B	1065BDNA1B	Meeting Room Kitchen Sink - Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Wooroloo Hall, Lot 45 Government Road, Wooroloo WA 6558	Wooroloo	3119BDNA2B	3119BDNA2B	Electrical Switchboard Interior Lining - visible fibres	0.5	YES	Damaged, not friable	Yes	MODERATE	Seal or remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal or remove and replace with non ACM product	5/08/2024	CEO	5/02/2025

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
5/02/2024	Wooroloo Hall, Lot 45 Government Road, Wooroloo WA 6558	Wooroloo	3119BDNA2B	3119BDNA2B	Ladies Toilet Ceiling & Walls	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Wooroloo Hall, Lot 45 Government Road, Wooroloo WA 6558	Wooroloo	3119BDNA2B	3119BDNA2B	Male Toilet Urinal - Blackjack spray resin	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Wooroloo Hall, Lot 45 Government Road, Wooroloo WA 6558	Wooroloo	3119BDNA2B	3119BDNA2B	Male Toilet Ceiling & Walls	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
5/02/2024	Wooroloo Hall, Lot 45 Government Road, Wooroloo WA 6558	Wooroloo	3119BDNA2B	3119BDNA2B	Kitchen Ceiling Panels	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
6/02/2024	Depot Mechanical Workshop, 25 Darkan Street, Mundaring WA 6073	Mundaring	2549BDNA2B	2549BDNA2B	Toilets & Change Room Urinal Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	5/02/2029
6/02/2024	Depot Administration Building, 25 Darkan Street, Mundaring WA 6073	Mundaring	2549BDNA1B	2549BDNA1B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Depot Vehicle Storage Shed, 25 Darkan Street, Mundaring WA 6073	Mundaring	2549BDNA4B	2549BDNA4B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Depot Dog/Cat Pound, 25 Darkan Street, Mundaring WA 6073	Mundaring	2549BDNA7B	2549BDNA7B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Eaves & Wall Panel	35	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Home Team Ceiling	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Panel Behind Hot Water Tank	4	YES	Damaged, not friable	Yes	MODERATE	Encapsulate crack or remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Encapsulate crack or remove and replace with non-ACM product	6/08/2024	CEO	6/02/2025
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Internal Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Pavilion Ceiling's	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Sawyers Valley Hall & Change Rooms, 20 Leather Green, Sawyers Valley WA 6074	Sawyers Valley	991005BDNA4B	991005BDNA4B	Club Storeroom Kitchen Sink Blackjac Spray Resin Backing (Large Storeroom)	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	N/A	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Bailup Equestrian Centre Clubrooms, Bailup Road, Wooroloo WA 6558	Wooroloo	3130BDNA2B	3130BDNA2B	Shadowline External Cladding	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Bailup Equestrian Centre Clubrooms, Bailup Road, Wooroloo WA 6558	Wooroloo	3130BDNA2B	3130BDNA2B	Vinyl Tiles throughout underneath Carpet and Linoleum	60	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Instruct Club members to not use the BBQ within 2m of the building. Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Instruct Club members not to use the BBQ within 2m of the building	2/04/2024	CEO	6/02/2025
6/02/2024	Bailup Equestrian Centre Clubrooms, Bailup Road, Wooroloo WA 6558	Wooroloo	3130BDNA2B	3130BDNA2B	Infill Panels Below Windows	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Bailup Equestrian Centre Toilets, Bailup Road, Wooroloo WA 6558	Wooroloo	3130BDNA1B	3130BDNA1B	Unknown - Unable to Access	0	NO	N/A	N/A	N/A	N/A	Proceed with caution until building can be inspected for ACM by a competent person	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Away Changeroom Ceiling	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Home Changeroom Ceiling	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Oval Perimeter Fencing & Ridge Capping	30	YES	Damaged and deteriorating	Yes	MODERATE	Remove vegetation from fence to prevent material from becoming friable. Remove and replace with non-ACM product.	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Shire to coordinate with homeowner over ACM hazard and suitable control measures. Remove vegetation from all fencing. Remove and replace with non-ACM product.	6/02/2024	CEO	6/02/2025
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Kiosk Ceilings	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Ladies Toilet Ceiling	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Male Toilet Ceiling	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Male Toilet Urinal Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Mount Helena Changerooms (Elsie Austin), 7 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA1B	3071BDNA1B	Water Storage & Rear Storage Room Ceiling	10	YES	Intact, not friable	No, if undisturbed	LOW	Seal the ceiling to prevent deterioration. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal the ceiling to prevent deterioration.	6/11/2024	CEO	6/02/2029
6/02/2024	Mundaring Rec Ground Pavilion - Changerooms, Lot 12770 Mundaring Weir, Mundaring WA 6073	Mundaring	2538BDNA2B	2538BDNA2B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Lake Leschenaultia - Breezeway Office, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA1B	3088BDNA1B	Shadowline Cladding Storage Area	50	YES	Damaged, not friable	Yes	MODERATE	Seal or encapsulate damaged panel below hose hook. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal damaged area and instruct workers/contractors of ACM hazard	5/08/2024	CEO	6/02/2025

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
6/02/2024	Lake Leschenaultia - Breezeway Office, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA1B	3088BDNA1B	External Eaves	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	6/02/2029
6/02/2024	Lake Leschenaultia - Café Kiosk, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA1B	3088BDNA1B	Main Cafe & Servery Ceiling	40	YES	Intact, not friable	No, if undisturbed	LOW	Seal around right-angle bracket (L shape) to prevent deterioration	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal around right-angle bracket (L shape) to prevent deterioration	6/08/2024	CEO	6/02/2025
6/02/2024	Lake Leschenaultia - Ticket Office (Entry Kiosk), 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA9B	3088BDNA9B	Internal Cladding Panels	20	YES	Intact, not friable	No, if undisturbed	LOW	Testing recommended. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Testing required	6/08/2024	CEO	6/02/2029
6/02/2024	Lake Leschenaultia - Change Room/Toilets, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA2B	3088BDNA2B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Lake Leschenaultia - Camping Toilet Block 1, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA8B	3088BDNA8B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
6/02/2024	Lake Leschenaultia - Camping Toilet Block 2, 2135 Rosedale Road, Chidlow WA 6556	Chidlow	3088BDNA6B	3088BDNA6B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
7/02/2024	Administration & Civic Complex, 7000 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA3B	991005BDNA3B	Floor Safe Insulation	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Administration & Civic Complex, 7000 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA3B	991005BDNA3B	Civic Room Bar Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Albert Facie Mundaring Library, 1 Nichol Street, Mundaring WA 6073	Mundaring	2076BDNA2B	2076BDNA2B	External Eaves	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Albert Facie Mundaring Library, 1 Nichol Street, Mundaring WA 6073	Mundaring	2076BDNA2B	2076BDNA2B	Vinyl Tile Encapsulated Under Carpet	150	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
7/02/2024	Mundaring & Lesser Hall, Lot 46 Nichol Street, Mundaring WA 6073	Mundaring	2076BDNA1B	2076BDNA1B	Foyer Male Toilet Urinal Blackjack Spray Resin Backing	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring & Lesser Hall, Lot 46 Nichol Street, Mundaring WA 6073	Mundaring	2076BDNA1B	2076BDNA1B	Stage, Jacoby Entrance & Storerooms Ceiling	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Vacant Block, 8 Craig Street, Mundaring WA 6073	Mundaring	301	301	Boundary Fence & Ridge Capping	150	YES	Damaged and deteriorating	Yes	HIGH	Remove vegetation from fence to prevent further damage and material becoming friable Emu bob around the site to remove ACM debris. Fence panel on ground deteriorating further via foot traffic Remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Remove vegetation from fence to prevent further damage and material becoming friable Emu bob around the site to remove ACM debris. Fence panel on ground deteriorating further via foot traffic Remove and replace with non-ACM product	7/09/2024	CEO	7/02/2024
7/02/2024	The Hub of the Hills, 11 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA2B	2534BDNA2B	Cleaners Store Room Vinyl Tiles	8	YES	Intact, not friable	No, if undisturbed	LOW	Testing required Seal or remove and replace with non-ACM product Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Testing required Seal or remove and replace with non-ACM product	7/11/2024	CEO	7/02/2025
7/02/2024	The Hub of the Hills, 11 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA2B	2534BDNA2B	Electrical Switchboard & Lining - Fire Hose Cupboard	1	YES	Intact, not friable	Yes	MODERATE	Seal damaged area or remove and replace with non-ACM product Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal damaged panels to prevent further deterioration	7/09/2024	CEO	7/02/2025
7/02/2024	The Hub of the Hills, 11 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA2B	2534BDNA2B	Stage Underfloor Packers/ Spacers	0.5	YES	Damaged and deteriorating	Yes	HIGH	Testing required Seal to prevent deterioration Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Testing required Seal to prevent deterioration Monitor and review for wear and damages	7/09/2024	CEO	7/02/2025
7/02/2024	The Hub of the Hills, 11 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA2B	2534BDNA2B	Rear Stage & Kitchen Store Room Vinyl Tiles	30	YES	Intact, not friable	No, if undisturbed	LOW	Unable to access Server Room, condition unknown Monitor and review for wear and damages. Consider sealing or removal with Cleaners Store sealing process.	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Consider including the same remediation works with Cleaners Store Room controls.	7/11/2024	CEO	7/02/2025
7/02/2024	CWA Building & Toilets, 3280 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA7B	2521BDNA7B	Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
7/02/2024	CWA Building & Toilets, 3280 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA7B	2521BDNA7B	External Cladding	80	YES	Intact, not friable	No, if undisturbed	LOW	Some panels have been replaced with non-ACM product, treat whole exterior as ACM product Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	CWA Building & Toilets, 3280 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA7B	2521BDNA7B	Interior Cladding Walls and Ceiling	200	YES	Intact, not friable	Yes	MODERATE	Seal exposed ACM around sink. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal exposed ACM around sink	7/09/2024	CEO	7/02/2025
7/02/2024	CWA Building & Toilets, 3280 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA7B	2521BDNA7B	Kitchen Sink Blackjacket Spray Resin Backing (Resprayed Silver)	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Harry Riseborough Oval Pavilion & Changerooms, 61-63 Hartung Street, Mundaring WA 6073	Mundaring	2060BDNA2B	2060BDNA2B	Telstra Pit	1	YES	Damaged and deteriorating	Yes	MODERATE	Seal or remove and replace with a non-ACM product. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal or contact Telstra to remove and replace with a non-ACM product	7/09/2024	CEO	7/02/2025
7/02/2024	Harry Riseborough Oval Pavilion & Changerooms, 61-63 Hartung Street, Mundaring WA 6073	Mundaring	2060BDNA2B	2060BDNA2B	Female Toilet Ceiling	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Harry Riseborough Oval Pavilion & Changerooms, 61-63 Hartung Street, Mundaring WA 6073	Mundaring	2060BDNA2B	2060BDNA2B	Home Changerooms Ceiling	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Harry Riseborough Oval Pavilion & Changerooms, 61-63 Hartung Street, Mundaring WA 6073	Mundaring	2060BDNA2B	2060BDNA2B	Storeroom Ceiling	5	YES	Intact, not friable	Yes	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Harry Riseborough Oval Pavilion & Changerooms, 61-63 Hartung Street, Mundaring WA 6073	Mundaring	2060BDNA2B	2060BDNA2B	Away Changerooms Ceiling	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Visitor Centre & HHS Museum, 7250 Great Eastern Highway WA 6073	Mundaring	991005BDNA2B	991005BDNA2B	Entrance Ceiling Panels	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Facia Boards & Eaves	60	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Consider encapsulating to prevent damage. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Gallery 2 Cupboard Ceiling	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	External Storeroom Ceiling & Wall Cladding	30	YES	Damaged and friable	Yes	HIGH	Remove and replace with non-ACM product Items stored against unsealed ACM can cause fibres to be released and possibly contaminated. Atmospheric testing required to determine levels of contamination of room and items stored within.	Restrict access to competent persons who can advise on and remove the asbestos hazard. Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Restrict access to External Storeroom to competent persons only. Do not remove any contents before identifying if it has been contaminated.	7/04/2024	CEO	7/02/2025
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Toilet Ceiling	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
7/02/2024	Mundaring Post Office Building (Art Centre), 7190 Great Eastern Highway, Mundaring WA 6073	Mundaring	991005BDNA1B	991005BDNA1B	Disabled Toilet Ceiling	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	7/02/2029
8/02/2024	Brown Park Community Centre, 116 Salisbury Road, Swan View WA 6056	Swan View	187BDNA1B	187BDNA1B	Brown Park Kitchen Sink Blackjack Spray Resin Backing	15	YES	Intact, not friable	No, if undisturbed	LOW	Consider encapsulating to prevent damage. Island bar bench considered the same as sink. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Brown Park Community Centre, 116 Salisbury Road, Swan View WA 6056	Swan View	187BDNA1B	187BDNA1B	Male Toilets & Changeroom Urinal Blackjack Spray Resin Backing	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
8/02/2024	Bruce Douglas Sporting Pavilion, Lot 156 Beresford Gardens, Swan View WA 6056	Swan View	120BDNA1B	120BDNA1B	Home Changeroom Urinal Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Bruce Douglas Sporting Pavilion, Lot 156 Beresford Gardens, Swan View WA 6056	Swan View	120BDNA1B	120BDNA1B	Away Changeroom Urinal Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Bruce Douglas Sporting Pavilion, Lot 156 Beresford Gardens, Swan View WA 6056	Swan View	120BDNA1B	120BDNA1B	Male Toilets Urinal Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Octagonal Hall, 52 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1140BDNA1B	1140BDNA1B	Exterior Electrical Switchboard	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Octagonal Hall, 52 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1140BDNA1B	1140BDNA1B	Interior Electrical Switchboard & Lining	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Octagonal Hall, 52 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1140BDNA1B	1140BDNA1B	Kitchen Ceilings	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Darlington Halls (Main Hall & Lesser Hall), Lot 37 Pine Terrace, Darlington WA 6070	Darlington	1065BDNA3B	1065BDNA3B	Stage Switchboard	1	YES	Intact, not friable	No, if undisturbed	LOW	Testing has been conducted, presumed ACM as test results unknown. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	Yes - Results unknown	Yes	Katherine Kempin, Monika Thomas	Locate test results or re-test to confirm the presence of ACM	8/09/2024	CEO	8/02/2025
8/02/2024	Darlington Halls (Main Hall & Lesser Hall), Lot 37 Pine Terrace, Darlington WA 6070	Darlington	1065BDNA3B	1065BDNA3B	Facia Panels		YES	Intact, not friable	No, if undisturbed	LOW	Encapsulate or seal to prevent deterioration. Testing has been conducted, presumed ACM as test results unknown. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	Yes - Results unknown	Yes	Katherine Kempin, Monika Thomas	Locate test results or re-test to confirm the presence of ACM	8/09/2024	CEO	8/02/2025
8/02/2024	Parkerville Hall, Lot 316 Riley Road, Parkerville WA 6081	Parkerville	2029BDNA3B	2029BDNA3B	Infill Panels to Stage Stairs	3	YES	Intact, not friable	No, if undisturbed	LOW	Seal/encapsulate or remove and replace with non-ACM product. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Testing required. Seal/ encapsulate or remove and replace with non-ACM product.	8/10/2024	CEO	8/02/2025
8/02/2024	Parkerville Hall, Lot 316 Riley Road, Parkerville WA 6081	Parkerville	2029BDNA3B	2029BDNA3B	Kitchen Sink Blackjack Spray Resin Backing	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
8/02/2024	Parkerville Hall, Lot 316 Riley Road, Parkerville WA 6081	Parkerville	2029BDNA3B	2029BDNA3B	Male Toilet Urinal Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Parkerville Hall, Lot 316 Riley Road, Parkerville WA 6081	Parkerville	2029BDNA3B	2029BDNA3B	Electrical Switchboard - unable to access	1	YES	Unknown	No, if undisturbed	LOW	Exercise caution when accessing electrical switchboard, ACM identification unknown	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Identify if ACM is present before any electrical work is conducted.	8/02/2025	CEO	8/02/2025
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Home Changerooms Ceiling	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Female Toilets Ceiling	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Visitors Changeroom Ceiling	30	YES	Damaged, not friable	Yes	MODERATE	Water damaged. Consider removal and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Consider removal and replace with non-ACM product	8/11/2024	CEO	8/02/2025
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	External Eaves	8	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Male Toilet Ceiling	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	8/02/2029
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Hot Water Tank Storeroom Ceiling	2	YES	Intact, not friable	No, if undisturbed	LOW	Seal or remove and replace with non-ACM product. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal ceiling to prevent damage	8/11/2024	CEO	8/02/2025
8/02/2024	Parkerville Oval Changerooms, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA2B	2022BDNA2B	Club Room Store Ceiling	4	YES	Intact, not friable	No, if undisturbed	LOW	Seal or remove and replace with non-ACM product. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal ceiling to prevent damage	8/11/2024	CEO	8/02/2025
8/02/2024	Parkerville Oval Pavilion, 580 Seaborne Street, Parkerville WA 6081	Parkerville	2022BDNA1B	2022BDNA1B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
9/02/2024	Marloo Hall Theatre, 20 Marloo Road, Greenmount WA 6056	Greenmount	131BDNA1B	131BDNA1B	Male Toilet Urinal Blackjack Spray Resin Backing	3	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
9/02/2024	Marloo Hall Theatre, 20 Marloo Road, Greenmount WA 6056	Greenmount	131BDNA1B	131BDNA1B	Green Room Kitchen Ceiling & Walls	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Kitchen & Dining Room Ceiling	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Front Living Room Fireplace Tile Grout	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Training Room Toilet Walls & Ceiling	8	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Training Room Toilet Tile Grout	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Laundry Ceiling & Wall Cladding	15	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Laundry Walls Tilux Printed Panels	15	YES	Intact, not friable	No, if undisturbed	LOW	Seal exposed holes. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal exposed holes	9/10/2024	CEO	9/02/2025
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Laundry Room Tile Grout	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Kitchen Fireplace Tiles Grout	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	Laundry & Main Meeting Room, Toilet External Cladding	50	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Dwelling - KSP Writers School - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA2B	101BDNA2B	External Eaves	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
9/02/2024	Dwelling - KSP Writers School - Office - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA3B	101BDNA3B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
9/02/2024	Dwelling - KSP Writers School - Cabin #1 - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA1B	101BDNA1B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
9/02/2024	Dwelling - KSP Writers School - Cabin #2 - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA4B	101BDNA4B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
9/02/2024	Dwelling - KSP Writers School - Cabin #3 - Megalong, 11 Old York Road, Greenmount WA 6056	Greenmount	101BDNA5B	101BDNA5B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
9/02/2024	First Friends Playgroup & Swan View Child Health Clinic, 84 Gladstone Avenue, Swan View WA 6056	Swan View	179BDNA1B	179BDNA1B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	First Friends Playgroup & Swan View Child Health Clinic, 84 Gladstone Avenue, Swan View WA 6056	Swan View	179BDNA1B	179BDNA1B	Storeroom Vinyl Floor Tiles	25	YES	Damaged and deteriorating	Yes	MODERATE	Seal to prevent further damage or remove and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal to prevent further damage	9/11/2024	CEO	9/02/2025
9/02/2024	First Friends Playgroup & Swan View Child Health Clinic, 84 Gladstone Avenue, Swan View WA 6056	Swan View	179BDNA1B	179BDNA1B	Toilet Floor Tiles Grout	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	First Friends Playgroup & Swan View Child Health Clinic, 84 Gladstone Avenue, Swan View WA 6056	Swan View	179BDNA1B	179BDNA1B	Vulcan Heater Gaskets	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	First Friends Playgroup & Swan View Child Health Clinic, 84 Gladstone Avenue, Swan View WA 6056	Swan View	179BDNA1B	179BDNA1B	Swan View Child Health Clinic Toilet Tile Grout	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Glen Forrest Community Kindergarten & Family Playgroup & Health Centre, 47 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA6B	1122BDNA6B	Playroom Sink Blackjack Spray Resin Backing	1	YES	Intact, not friable	No, if undisturbed	LOW	Consider encapsulating to prevent damage when storing items. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liabile to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
9/02/2024	Glen Forrest Kindergarten & Family Playgroup & Health Centre, 47 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA6B	1122BDNA6B	Health Centre Kitchen Sink Black Spray Resin Backing	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Glen Forrest Kindergarten & Family Playgroup & Health Centre, 47 Marnie Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA6B	1122BDNA6B	Health Centre Eaves	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Darlington Family Playgroup, Lot 556 Lionel Road, Darlington WA 6070	Darlington	1116BDNA1B	1116BDNA1B	Eaves & Facia Panels	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Darlington Family Playgroup, Lot 556 Lionel Road, Darlington WA 6070	Darlington	1116BDNA1B	1116BDNA1B	External Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Darlington Family Playgroup, Lot 556 Lionel Road, Darlington WA 6070	Darlington	1116BDNA1B	1116BDNA1B	Electrical Switchboard & Ceramic Fuses	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
9/02/2024	Darlington Tennis Club Pavilion, Lot 1 Owen Road, Darlington WA 6070	Darlington	1060BDNA1B	1060BDNA1B	Tennis Court Electrical Switchboard & Fuses	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	9/02/2029
12/02/2024	Mundaring Child Health Clinic & Toy Library, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA1B	2534BDNA1B	External Eaves	50	YES	Intact, not friable	No, if undisturbed	LOW	Keep vegetation away from ACM product to prevent damage and material becoming friable. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Schedule regular maintenance of vegetation to be kept away from ACM	12/08/2024	CEO	12/02/2025
12/02/2024	Mundaring Child Health Clinic & Toy Library, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA1B	2534BDNA1B	Toy Library Toilet Floor Tile Grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Mundaring Child Health Clinic & Toy Library, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA1B	2534BDNA1B	Child Clinic Toilet Floor Tile Grout	10	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Mundaring Child Health Clinic & Toy Library - Garage, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA6B	2534BDNA6B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
12/02/2024	Mundaring Child Health Clinic & Toy Library - Shed #1, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA8B	2534BDNA8B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	Mundaring Child Health Clinic & Toy Library - Shed #2, 12 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA7B	2534BDNA7B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	The Rise Office (Wahroonga House), 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA4B	2534BDNA4B	Main Dining Room Pyrox Heater Flue	2	YES	Intact, not friable	No, if undisturbed	LOW	Manufacturer and installation date of heater unknown, presumed ACM could be present (pre 1980 could contain ACM) Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	The Rise Office (Wahroonga House), 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA4B	2534BDNA4B	Lounge Room Rinnai Heater Flue	2	YES	Intact, not friable	No, if undisturbed	LOW	Manufacturer date and installation of heater unknown presumed ACM could be present (pre 1990 could contain ACM) Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	The Rise Office (Wahroonga House), 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA4B	2534BDNA4B	Perimeter & Partition Fencing & Ridge Capping	250	YES	Damaged and friable	Yes	HIGH	Remove all vegetation from fencing and ridge capping Remove all ACM fence and ridge capping and replace with non-ACM product	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Remove all vegetation from fencing and ridge capping. Schedule for removal to occur within 12 months	12/08/2024	CEO	12/02/2025
12/02/2024	The Rise Office (Wahroonga House), 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA4B	2534BDNA4B	Lounge Entrance Eaves	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	The Rise (Wahroonga House) - Craft Room, 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA9B	2534BDNA9B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	The Rise (Wahroonga House) - Transportable Offices, 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA5B	2534BDNA5B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	The Rise (Wahroonga House) - Long Garden Shed, 2 Craig Street, Mundaring WA 6073	Mundaring	2534BDNA10B	2534BDNA10B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
12/02/2024	Mundaring Weir Hall - Arts & Crafts, Lot 7783 Hall Road, Mundaring WA 6073	Mundaring	2552BDNA1B	2552BDNA1B	Interior Switchboard & Lining	0.5	YES	Intact, not friable	No, if undisturbed	MODERATE	Seal lining or remove and replace with non-ACM product. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Seal lining or remove and replace with non-ACM product	12/09/2024	CEO	12/02/2025
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Tea Room Ceiling & Walls (Addition)	60	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Male & Female Toilets Internal Cladding Ceiling	30	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Male & Female Toilets Walls	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Studio 4 Wall to back of Female Toilets	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Veranda Eaves/Ceiling	150	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Toilets Exterior Cladding & Batons	25	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA3B	2595BDNA3B	Electrical Switchboard	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Craigie House - Mundaring Adult Creative Centre - Store Room, 3 Craigie Place, Mundaring WA 6073	Mundaring	2595BDNA6B	2595BDNA6B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	External Electrical Switchboard & Fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Consider encapsulating to prevent damage. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	Children's Sink Blackjack Spray Resin Backing	1	YES	Intact, not friable	No, if undisturbed	LOW	Consider encapsulating to prevent damage. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	Toilet Tile Grout	40	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	Ceiling Panels	120	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Eastern Hills Playgroup & Community Kindergarten, 14 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA7B	3071BDNA7B	Vinyl Tiles Under Linoleum	160	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Jar-Ree Scout Hall & Extension, Lot 5 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA4B	3071BDNA4B	Entrance Eaves	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Jar-Ree Scout Hall & Extension, Lot 5 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA4B	3071BDNA4B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Jar-Ree Scout Hall & Extension, Lot 5 Chidlow Street, Mount Helena WA 6082	Mount Helena	3071BDNA4B	3071BDNA4B	Meeting Room Sink Blackjack Spray Resin Backing	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Chidlow Hall, Lot 385 Old Northam Road, Chidlow WA 6556	Chidlow	3091BDNA2B	3091BDNA2B	Main Hall Ceiling & Batons	150	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Chidlow Hall, Lot 385 Old Northam Road, Chidlow WA 6556	Chidlow	3091BDNA2B	3091BDNA2B	Electrical Switchboard & Ceramic Fuses	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Chidlow Hall - Toilets, Lot 385 Old Northam Road, Chidlow WA 6556	Chidlow	3091BDNA3B	3091BDNA3B	N/A	0	NO	N/A	N/A	N/A	N/A	Non suspected	No	No	N/A	Katherine Kempin, Monika Thomas	N/A	N/A	N/A	N/A
12/02/2024	Chidlow Family Playgroup & Community Kindergarten/ Health Clinic, Lot 266 Northcote Street, Chidlow WA 6556	Chidlow	3093BDNA1B	3093BDNA1B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029

Date of Inspection	Address	Suburb	Property File LGIS Ref.	SWEK Asset No.	ACM Location	ACM Amount (m2)	ACM Presumed	ACM Condition	ACM Liable to damage or deterioration?	ACM Risk Level	Control Measures Recommended	Comments	Testing Required	Testing Conducted	Site Inspection Attachment	Inspected by	Remediation to be Implemented	Remediation Completed Before	Responsible Person	Re-assess Prior to
12/02/2024	Chidlow Family Playgroup & Community Kindergarten/ Health Clinic, Lot 266 Northcote Street, Chidlow WA 6556	Chidlow	3093BDNA1B	3093BDNA1B	Vulcan Heater Gaskets	4	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
12/02/2024	Chidlow Family Playgroup & Community Kindergarten/ Health Clinic, Lot 266 Northcote Street, Chidlow WA 6556	Chidlow	3093BDNA1B	3093BDNA1B	Children's Sink to Playroom Blackjack Spray Resin Backing	1	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	12/02/2029
13/02/2024	Glen Forrest Sporting Hall, Lot 143 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA4B	1122BDNA4B	Kitchen Sink Blackjack Spray Resin Backing	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	13/02/2029
13/02/2024	Glen Forrest Sporting Hall, Lot 143 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA4B	1122BDNA4B	External Cladding Facing Bowling Green	100	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	13/02/2029
13/02/2024	Glen Forrest Sporting Hall, Lot 143 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA4B	1122BDNA4B	Gable Front Entrance Panels	5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	13/02/2029
13/02/2024	Glen Forrest Sporting Hall, Lot 143 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA4B	1122BDNA4B	Electrical Switchboard to B Bowling Green	0.5	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	13/02/2029
13/02/2024	Glen Forrest Sporting Hall, Lot 143 McGlew Road, Glen Forrest WA 6071	Glen Forrest	1122BDNA4B	1122BDNA4B	Main Electrical Switchboard & Ceramic Fuses	2	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	13/02/2029
14/02/2024	Mundaring Scout Hall, 3045 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA2B	2521BDNA2B	Gable End Panels & Batons	20	YES	Intact, not friable	No, if undisturbed	LOW	Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	14/02/2029
14/02/2024	Mundaring Scout Hall, 3045 Jacoby Street, Mundaring WA 6073	Mundaring	2521BDNA2B	2521BDNA2B	Storeroom/ Garage Original Structure Exterior Cladding Panels & Batons	30	YES	Intact, not friable	No, if undisturbed	LOW	Remove items from panels to prevent damage and ACM becoming friable. Monitor and review for wear and damages	Removal by a licenced asbestos contractor during refurbishment or demolition	Yes, before disturbed	No	Yes	Katherine Kempin, Monika Thomas	Monitor in place	N/A	CEO	14/02/2029